

NATIONAL PACIFIC INSURANCE (TONGA) LTD

Suite 10, Level 2. TMF Business Centre.

Taufa'ahau Road. Nukualofa. Tonga

Private Bag 32. Tonga. T. +676 24066 F.+676 23707

List of Approved Engineers to issue Cyclone Engineers Certificates

Should you require your insurance policy to be extended to include cover for cyclones you must provide us with a cyclone certificate for your property (in form and substance, and from an engineer, acceptable to us). Set out below is a list of engineers who meet our requirements. If you choose to obtain a cyclone certificate from an engineer that is not on that list, we may not accept your cyclone certificate.

Name	Firm Name/Address	Phone/Email
Tahisi VEHIKITE	Kramer Ausenco Unit 2 Level 2 TMF Building, Taufa'ahau Road PO Box 938, Nuku'alofa, Tonga	(+676) 25212/ (+676) 25055 Email: tahisi.vehikite@kramerausenco.com
Lisiate 'Esau Tupou	Quality Design Limited Kolofo'ou, Nuku'alofa, Tonga	(+676) 874-1011/ (676) 22-279 Email: qualitydesign.tupu51@gmail.com
Maeakafa TU'INUKUAFE	SFL Group-Civil & Construction Nukunuku, tonga	(+676) 770-2118 Email: mtuinukuafe93@gmail.com
Blake KAITU'U* <i>(Subject to prior approval by NPI Tonga)</i>	Hwamstan Group Bay of Manumataongo, 676 Nukalofa, Tongatapu, Tonga.	(+676) 771-9813 Email: blake.plusarchidesign@gmail.com

All Certificates must be accompanied with photographs in both digital and printed format and must show:

- View of the overall Property for identification purposes
- Overhead view of the Roof and Fastenings
- View of Purlins (where physically possible)
- View Rafters and Fastening
- View Windows including shutter brackets and actual shutters.

Our acceptance of the cyclone certificate does not constitute acceptance of any work or services provided by any engineer.

We are not liable for any claim, loss, damage, or costs suffered by any person howsoever arising in consequence of, or in any way related to, any work or services provided by any engineer. We make no guarantees, representations, or warranties in relation to any such work or services.